

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Toyota	Body Style:	Wagon
Model:	Corolla	Odometer:	106,657 Kms
Year:	2008	VIN:	7AT0H607X18034014

Under Carriage & Under Bonnet Inspection Comments

Seats:	Good
Carpets:	Good
Panels:	Scratch left rear panel
Dashboard:	Good

General Comments

Panels: Scrutch lett real panel			
Dashboard: Good			
Engine Timing Mechanism:	Timing Chain		
Evidence of Cam Belt Replacement:	Not Applicable		
Replaced At (odometer reading):			
Road Conditions During Test Drive:	Wet		

Electrical	Transmis	Transmission & Drive		Engine		Tyres (lowest observed tread depth)	
Battery	Operation	1		Oil level		Left front	6 mm
Head lights	Noise			Smoke & fumes		Right front	6 mm
Tail lights	Clutch		•	Performance		Left rear	6 mm
Indicators	CV joints			Noise		Right rear	6 mm
Dashboard warning lights	Wheel bea	arings		Cooling System		Spare	Yes
Wipers (front & rear)	Wheel bal	ance				Tools	
Window winder FL	Brakes			Coolant condition		Interior	
Window winder FR				Performance			
Window winder RL	Performar	nce		Radiator / Hoses (visual)		AC Operation	
	Hand Brak	ke in the second se		Suspension		Heater fan	
	Keys & Lo	ocking		Suspension performance	V	Seatbelts	
	Central lo	cking		Steering performance		Horn	
CD (basic test only)	Remote lo	-		Shock absorbers		Turners Certified № ✓ = Pass • = Not applicab	X = Fail
Reversing camera	Number o	of keys	1	Inspected by: John Linds	ay		9 Dec 2018

Signature: