

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Mazda	Body Style:	Wagon
Model:	Atenza	Odometer:	60,601 Kms
Year:	2008	VIN:	7AT0C139X18100174

Under Carriage & Under Bonnet Inspection Comments Battery load test ok

Seats:	Average		
Carpets:	Average		
Panels:	Average		
Dashboard:	Average		
Engine Timir	ng Mechanism:	Timing Chain	

Evidence of Cam Belt Replacement:

Not Applicable

Wet

Replaced At (odometer reading):

Road Conditions During Test Drive:

General Comments

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 4.0 mm
Head lights	Noise	Smoke & fumes	Right front 4.0 mm
Tail lights	Clutch	Performance	Left rear 7.0 mm
Indicators	CV joints	Noise	Right rear 7.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle
Reversing camera •	Number of keys 1	Inspected by: Greg Morgan	Date: 15 Jan 2019

Name:

Signature: