



# Turners Certified Imports 50 Point Check

Report ID: 18,871,842

Version: 1

Created: 16 Jan 2019

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Volkswagen Body Style: Hatchback  
Model: Polo Odometer: 39,676 Kms  
Year: 2009 VIN: WVVZZZ9NZ9U016633

Under Carriage & Under Bonnet Inspection CommentsGeneral Comments

Seats: Good

Carpets: Good

Panels: Good

Dashboard: Good

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Replaced At (odometer reading):

Road Conditions During Test Drive: Wet

**Electrical**

Battery ☒  
Head lights ☒  
Tail lights ☒  
Indicators ☒  
Dashboard warning lights ☒  
Wipers (front & rear) ☒  
Window winder FL ☒  
Window winder FR ☒  
Window winder RL ☒  
Window winder RR ☒  
Rear view mirrors ☒  
Radio (basic test only) ☒  
CD (basic test only) ☒  
Reversing camera ☒

**Transmission & Drive**

Operation ☒  
Noise ☒  
Clutch ☒  
CV joints ☒  
Wheel bearings ☒  
Wheel balance ☒

**Brakes**

Performance ☒  
Hand Brake ☒

**Keys & Locking**

Central locking ☒  
Remote locking ☒  
Number of keys

**Engine**

Oil level ☒  
Smoke & fumes ☒  
Performance ☒  
Noise ☒

**Cooling System**

Coolant condition ☒  
Performance ☒  
Radiator / Hoses (visual) ☒

**Suspension**

Suspension performance ☒  
Steering performance ☒  
Shock absorbers ☒

**Tyres** (lowest observed tread depth)

Left front  mm  
Right front  mm  
Left rear  mm  
Right rear  mm  
Spare   
Tools ☒

**Interior**

AC Operation ☒  
Heater fan ☒  
Seatbelts ☒  
Horn ☒

**Turners Certified Key**

✓ = Pass X = Fail  
• = Not applicable for this vehicle

Inspected by: Hamish McDonald

Date: 16 Jan 2019

I have read and understood this condition guide.

Name: .....

Signature: .....