

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Toyota	Body Style:	Van
Model:	Hiace	Odometer:	99,419 Kms
Year:	2014	VIN:	7AT0H60FX19155726

Under Carriage & Under Bonnet Inspection Comments

Seats:	Average
Carpets:	Good
Panels:	Left front door scratches
Dashboard:	Good
	Combolt

General Comments

Dashboard: Good	
Engine Timing Mechanism:	Cambelt
Evidence of Cam Belt Replacement:	No
Replaced At (odometer reading):	
Road Conditions During Test Drive:	Dry

Road Conditions	During	Test Drive:	-

Electrical	Transm	Transmission & Drive		Engine		Tyres (lowest observed tread depth)		
Battery	Operatio	on		Oil level		Left front	6	mm
Head lights	Noise			Smoke & fumes		Right front	6	mm
Tail lights	Clutch		•	Performance		Left rear	6	mm
Indicators	CV joint	S		Noise		Right rear	5	mm
Dashboard warning lights	Wheel b	pearings		Cooling System		Spare	Yes]
Wipers (front & rear)	Wheel b	balance		Coolant condition		Tools	V	
Window winder FL	Brakes			Performance		Interior		
Window winder FR								
Window winder RL	Perform	nance		Radiator / Hoses (visual)		AC Operation		
Window winder RR	Hand Br	rake		Suspension		Heater fan		
Rear view mirrors	Keys &	Locking		Suspension performance		Seatbelts		
Radio (basic test only)	Central	locking	1	Steering performance		Horn		
CD (basic test only)		locking		Shock absorbers			X = Fail	
Reversing camera	Number	r of keys	1	Inspected by: John Linds	ay	• = Not applicat	ble for this v 4 Jan 2019	ehicle

Name: