

Turners Certified Imports 50 Point Check

Report ID: 18,879,301

Version: 1

Created: 04 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

accredited inspection agency and been test di			
Make: Toyota	Body Sty	_{yle:} Van	S
Model: Hiace	Odomet	er: 43,961 Kms	
Year: 2010	VIN:	7AT0H60FX19154183	
Under Carriage & Und	der Bonnet Insr	pection Comments	_] P
Rear Tyres shoulders we			
] [E

Seats:	Good
Carpets:	Good
Panels:	Good
Dashboard:	Good



Engine Timing Mechanism:


Evidence of Cam Belt Replacement:


Replaced At (odometer reading):


Road Conditions During Test Drive:

Dry









Tyres (lowest observed tread