

Turners Certified Imports 50 Point Check

Report ID: 18,879,726

Version:

Created: 07 Feb 2019

Note: This report is not a warranty

CERTIFIED diagramment diagramm	nostic testing undertaken. The vehi edited inspection agency and been te	cle has undergone a thorough co st driven up to 50km/h from cold.	mpliance check by an NZTA
Model: Polo	Body Style: Hatchback Odometer: 4,947 Kms VIN: WVWZZZ9NZ9U002981 unet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading):	Cambelt No
		Road Conditions During Test Drive:	Tyres (lowest observed tread
Electrical	Transmission & Drive	Engine	depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL •	Hand Brake		Heater fan
Window winder RR •	naliu biake	Suspension	
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking •	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

Reversing camera

Inspected by: John Lindsay

2

Number of keys

Date: 07 Feb 2019