

Basic Vehicle Condition Guide

Report ID: 56,103

Version: 2

Engine

30 Jan 2019 Created:

Pass


N/A

Fail

Make: Holden Model: Cruze **Body Style:** Hatchback Year: 2013 Registration: **GWA423 Reg Expiry:** 11 Dec 2019 WoF Expiry: **Odometer:** 15 Mar 2019 125,583 Kms **Good No:** 18879892 VIN: 6G1PD6EY8EL901784 Next Service: 5/10/2019 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

	Conditions	During	ı Bodv	Inspection
--	------------	--------	--------	------------

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	<u>S</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Oil level Smoke & fumes 1 Performance / Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch J CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 8.0 Right front 8.0 mm Left rear 8.0 mm Right rear 8.0 mm Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only) ~ Reversing camera ~

Inspected by: Date:

I have read and understood this condition guide.

Name:

Signature:

24 Jan 2019