

Turners Certified Imports 50 Point Check

 Report ID:
 18,891,245

 Version:
 1

 Created:
 04 Mar 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Subaru	Body Style:	SUV
Model:	Forester	Odometer:	99,356 Kms
Year:	2009	VIN:	7AT0GF17X19040460

Under Carriage & Under Bonnet Inspection Comments

Seats:	driver seat worn	
Carpets:	Average	
Panels:	Average	
Dashboard:	Average	
Engine Timii	ng Mechanism:	Cambelt

General Comments

Dashboard: Average	
Engine Timing Mechanism:	Cambelt
Evidence of Cam Belt Replacement:	No
Replaced At (odometer reading):	
Road Conditions During Test Drive:	Dry

Electrical	Transmission & Drive	Transmission & Drive		Engine		Tyres (lowest observed tread depth)		
Battery	Operation		Oil level		Left front	7	mm	
Head lights	Noise		Smoke & fumes		Right front	7	mm	
Tail lights	Clutch	•	Performance		Left rear	7	mm	
Indicators	CV joints		Noise		Right rear	7	mm	
Dashboard warning lights	Wheel bearings		Cooling System		Spare	Yes]	
Wipers (front & rear)	Wheel balance				Tools	V		
Window winder FL	Brakes		Coolant condition		Interior			
Window winder FR			Performance					
Window winder RL	Performance		Radiator / Hoses (visual)		AC Operation			
Window winder RR	Hand Brake		Suspension		Heater fan			
Rear view mirrors	Keys & Locking		Suspension performance	/	Seatbelts			
Radio (basic test only)	Central locking	•	Steering performance		Horn			
CD (basic test only)	Remote locking		Shock absorbers			X = Fail		
Reversing camera •	Number of keys	2	Inspected by: John Linds	ay	• = Not applicab	ole for this v	ehicle	

Name:

Signature: