

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Mazda	Body Style:	Sedan
Model:	Atenza	Odometer:	108,397 Kms
Year:	2013	VIN:	7AT0C139X19108448

Under Carriage & Under Bonnet Inspection Comments

	Seats:	Good		
	Carpets:	Average		
]	Panels:	Average		
	Dashboard:	Average		
	Engine Timi	ng Mechanism:	Timing Chain	

Evidence of Cam Belt Replacement:

Not Applicable

Dry

Replaced At (odometer reading):

Road Conditions During Test Drive:

General Comments

Electrical **Transmission & Drive** Engine Battery Operation Oil level **Head lights** Noise Smoke & fum Tail lights Clutch • Performance Indicators **CV** joints Noise Dashboard warning lights Wheel bearings **Cooling Sys** Wipers (front & rear) Wheel balance Coolant conc Window winder FL **Brakes** Performance Window winder FR Radiator / Ho Performance Window winder RL Hand Brake **Suspension** Window winder RR **Keys & Locking** Rear view mirrors Suspension p Radio (basic test only) **Central locking** Steering perf CD (basic test only) **Remote locking** Shock absorb 1 **Reversing camera** • Number of keys Inspected by: John Lindsay

	Tyres (lowest obse depth)	erved tread	
	Left front	7	mm
5	Right front	7	mm
	Left rear	7	mm
	Right rear	7	mm
n	Spare	Yes	
on	Tools	V	
	Interior		
s (visual)	AC Operation		
	Heater fan		
formance	Seatbelts		
formance mance	Horn		
s	Turners Certified I ✓ = Pass • = Not applical	X = Fail	ehicle

Name:

Signature:

Date: 26 Feb 2019