

Turners Certified Imports 50 Point Check

Report ID: 19,103,159

Version:


Created: 22 Feb 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED IMPORTED VEHICLES	diagnosti accredite	d inspection agency and b	e vehicle has und een test driven up	to 50km/h from colc	compliance check d.	by an N	ZIA
Make: Mazda Model: Axela Year: 2014 Under Carriage & Under	Odoi VIN:	r Style: Hatchback meter: 86,318 Kms 7AT0C13JX1910279: nspection Comments	Panels: Dashboard	Average Average Average d: Average	Timing Chain		
General Comments			Evidence o	of Cam Belt Replaceme At (odometer reading): ditions During Test Driv	W-+		
Electrical		Transmission & Drive	Engine		Tyres (lowest obsedepth)	rved tread	
Battery		Operation	Oil level		Left front	7	mm
Head lights		Noise	Smoke & fu	umes	Right front	7	mm
Tail lights		Clutch	• Performan	ice	Left rear	7	mm
Indicators		CV joints	Noise		Right rear	7	mm
Dashboard warning lights		Wheel bearings			Spare	No]

Battery	'
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	





Reversing camera

Inspected by: Andrew Loach

Date: 22 Feb 2019