

## Turners Certified Imports 50 Point Check

Report ID: 19,104,475

Version: 1

Created: 27 Feb 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

| IMPORTED VEHICLES             | accredited inspection agency          | / and been test driven up to | 50km/h from cold.                                | ce check by all NZTA  |  |
|-------------------------------|---------------------------------------|------------------------------|--|---|--|
| Make: Nissan<br>Model: Dualis | Body Style: SUV Odometer: 106,000 Kms | Seats.                       | Good   |   |  |
| Year: 2008                    | VIN: 7AT0DH7HX1                       | 19000247 Carpets.            |  |   |  |
| Under Carriage & Und          | er Bonnet Inspection Commen           | Panels:                      | Good   |   |  |
|                               |                                       | Dashboard:                   | Good   |   |  |
|                               |                                       | Engine Timing                | g Mechanism.                                     | ng Chain  |  |
| General Comments              |                                       | Evidence of Ca               | Evidence of Cam Belt Replacement: Not Applicable |   |  |
|                               |                                       | Replaced At (d               | odometer reading):                               |   |  |
|                               |                                       | Road Condition               | ons During Test Drive: Dry                       |   |  |
| Electrical                    | Transmission & Dri                    | ive Engine                   | <b>Tyres</b> depth)                              | (lowest observed tread  |  |
| Battery                       | Operation                             | Oil level                    | Left fro   | ont 4 mm  |  |
| Head lights                   | Noise                                 | Smoke & fume                 | es Right f                                       | front 4 mm  |  |
| Tail lights                   | Clutch                                | Performance                  | Left re  | ear 5 mm  |  |
| Indicators                    | CV joints                             | Noise                        | Right  | rear 5 mm   |  |
| Dashboard warning ligh        | ts Wheel bearings                     | Cooling Syste                | Spare  | Yes   |  |
| Wipers (front & rear)         | Wheel balance                         | Coolant condi                | Tools  |   |  |
| Window winder FL              | Brakes                                | Performance                  | Interio  | or  |  |
| Window winder FR              | Performance                           | Radiator / Hos               | ses (visual)                                     | peration  |  |
| Window winder RL              | Hand Brake                            |                              | Heater   |   |  |
| Window winder RR              | Tidild brake                          | Suspension                   | Seatbe   |   |  |
| Rear view mirrors             | Keys & Locking                        | Suspension pe                | erformance                                       |   |  |
| Radio (basic test only)       | Central locking                       | Steering perfo               | prmance Horn                                     |   |  |
| CD (basic test only)          | Remote locking                        | • Shock absorbe              | ers  | rs Certified Key Pass <b>X</b> = Fail Not applicable for this vehicle |  |
| Reversing camera              | Number of keys                        | 1 Inspected by:              | Bobby Zhong                                      | Date: 27 Feb 2019   |  |