

Turners Certified Imports 50 Point Check

Report ID: 19,107,311

Version:

25 Feb 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	accredited inspection	agency and been tes	st driven up to 50km/l	h from cold.	inpliance check	by all 142	-174
Make: Honda Body Style: Hatchback Model: FIT Odometer: 79,496 Kms Year: 2013 VIN: 7AT08G2YX19241577 Under Carriage & Under Bonnet Inspection Comments			Seats: Good Carpets: Good Panels: Good Dashboard: Good				
General Comments			Engine Timing Mechan Evidence of Cam Belt Replaced At (odomet Road Conditions Duri	Replacement:	Timing Chain Not Applicable Dry		
Electrical	Transmissio	on & Drive	Engine		Tyres (lowest obse	erved tread	
Battery	Operation		Oil level		Left front	5	mm
Head lights	Noise		Smoke & fumes		Right front	4	mm
Tail lights	Clutch	•	Performance		Left rear	6	mm
Indicators	CV joints		Noise		Right rear	5	mm
Dashboard warning ligh	wheel beari	ngs	Cooling System		Spare	N/A	
Wipers (front & rear)	Wheel balan	ce	Coolant condition		Tools		
Window winder FL	Brakes		Performance		Interior		
Window winder FR	Performance		Radiator / Hoses (visu	ual)	AC Operation	í	
Window winder RL	Hand Brake		(, <u>•</u>	Heater fan	ľ	
Window winder RR		•	Suspension	_	Seatbelts	ľ	
Rear view mirrors	Keys & Lock	ing	Suspension performa	ance 🚺	Horn		

Steering performance

Inspected by: Mathew Varghese

Shock absorbers

2

Turners Certified Key

X = Fail = Not applicable for this vehicle

Date: 25 Feb 2019

Signature:

✓ = Pass

•

Central locking

Remote locking

Number of keys

Radio (basic test only)

CD (basic test only)

Reversing camera