

Turners Certified Imports 50 Point Check

Report ID: 19,108,743


Version:


Created: 28 Feb 2019


Note: This report is not a warranty

	TIFIED D VEHICLES	diagnosti accredite	t is a guide only. Consider c testing undertaken. The d inspection agency and be	vehicle has unde en test driven up t	rgone a thorough co o 50km/h from cold.	ompliance check	by an NZTA
Model: Year:	2010	Odor VIN:	Style: Hatchback neter: 126,777 Kms 7AT0C13JX19100742 nspection Comments	Seats: Carpets: Panels: Dashboard:	Good Good Good		
General	Comments			Evidence of Replaced At	ing Mechanism: Cam Belt Replacement: t (odometer reading): tions During Test Drive:	Timing Chain Not Applicable Wet	
Electrica	I		Transmission & Drive	Engine		Tyres (lowest obsedepth)	rved tread
Battery			Operation	Oil level		Left front	5 mn
Hoad ligh	htc		Noise	Smoke & fu	mas	Pight front	5 mn









Inspected by:	Xinghui Lin	Date:	28 Feb 2019