

## **Turners Certified Imports 50 Point Check**

Report ID: 19,112,713

Version: 1

Created: 05 Mar 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:HondaBody Style:HatchbackModel:FITOdometer:76,751 KmsYear:2014VIN:7AT08G2YX19241433

**Under Carriage & Under Bonnet Inspection Comments** 

**General Comments** 

Seats:	driver seat worn
Carpets:	Average
Panels:	right rear door panel scratched
Dashboard:	Average

Engine Timing Mechanism:


Evidence of Cam Belt Replacement:


Replaced At (odometer reading):


Road Conditions During Test Drive:

Dry









Inspected by: Kyle Mills-Brown Date: 05 Mar 2019