

Turners Certified Imports 50 Point Check

Report ID: 19,119,647

Version: 2

Created: 27 May 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED diag accre	nostic testing undertaken. The veredited inspection agency and been t	nicle has undergone a thorough co est driven up to 50km/h from cold.	ompliance check by an NZTA
Make: Toyota Model: Isis Year: 2011 Under Carriage & Under Bor General Comments	Body Style: Odometer: 72,919 Kms VIN: 7AT0H658X19033302 Innet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading):	Timing Chain Not Applicable Dry
Electrical	Transmission & Drive	Road Conditions During Test Drive: Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

Reversing camera

Inspected by: Roger King

2

Number of keys

Date: 27 May 2019