

Turners Certified Imports 50 Point Check

Report ID: 19,123,369

Version:

Created: 16 Mar 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	ccredited inspection agency and been	test driven up to 50km/h from cold.	,	
Make: Subaru Body Style: Wagon Model: Exiga Odometer: 89,606 Kms Year: 2008 VIN: 7AT0GF1RX19005332 Under Carriage & Under Bonnet Inspection Comments General Comments		Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Cambelt No Dry	
Electrical	Transmission & Drive	Engine	Tyres (lowest observed depth)	d tread
Battery	Operation	Oil level	Left front	7 mm
Head lights	Noise	Smoke & fumes	Right front	7 mm
Tail lights	Clutch	Performance	Left rear	7 mm
Indicators	CV joints	Noise	Right rear	7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare	Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools	
Window winder FL	Brakes	Performance	Interior	
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation	
Window winder RL	Hand Brake		Heater fan	
Window winder RR	✓ I Mand Branc	Suspension	Seatbelts	
Rear view mirrors	Keys & Locking	Suspension performance	Horn	
Radio (basic test only)	Central locking	Steering performance	Hom	

Remote locking

Number of keys

CD (basic test only)

Reversing camera

2

Shock absorbers

Inspected by: Sudhin Ramachandran

Date: 16 Mar 2019

X = Fail = Not applicable for this vehicle

Turners Certified Key

✓ = Pass