

## Turners Certified Imports 50 Point Check

Report ID: 19,144,041

Version: 1

Created: 26 Mar 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

IMPORTED VEHICLES	ccredited inspection agency and been to	est driven up to 50km/h from cold.	impliance check by an NZTA
Make: Subaru	Body Style: Wagon	Seats: Good	
Model: Exiga	Odometer: 100,354 Kms	Carnete: Good	
Year: 2010	VIN: 7AT0GF1RX19009689	Carpets.	
Under Carriage & Under Bonnet Inspection Comments		Panels: Good	
		Dashboard: Good	
		Engine Timing Mechanism:	Cambelt
General Comments		Evidence of Cam Belt Replacement:	No
		Replaced At (odometer reading):	
		Road Conditions During Test Drive:	Dry
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 3 mm
Head lights	Noise	Smoke & fumes	Right front 3 mm
Tail lights	Clutch	Performance	Left rear 5 mm
Indicators	CV joints	Noise	Right rear 5 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake	Traditator / Froses (visual)	Heater fan
Window winder RR	I land blake	Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key  ✓ = Pass <b>X</b> = Fail  • = Not applicable for this vehicle
Reversing camera	Number of keys	Inspected by: Mathew Varghese	Date: 26 Mar 2019