

## **Turners Certified Imports 50 Point Check**

 Report ID:
 19,147,336

 Version:
 2

 Created:
 01 Apr 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Honda	Body Style:	Hatchback
Model:	FIT	Odometer:	51,787 Kms
Year:	2010	VIN:	7AT08G2YX19300046

Under Carriage & Under Bonnet Inspection Comments

	Seats:	Good		
	Carpets:	Good		
]	Panels:	Good		
	Dashboard:	Good		
	Engine Timir	ng Mechanism:	Timing Chain	

Not Applicable

Dry

Evidence of Cam Belt Replacement:

Replaced At (odometer reading):

Road Conditions During Test Drive:

**General Comments** 

Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)	<b>Tyres</b> (lowest observed tread depth)	
Battery	Operation	Oil level	Left front	L mm	
Head lights	Noise	Smoke & fumes	Right front	l mm	
ail lights	Clutch [	Performance	Left rear	h ww	
ndicators	CV joints	Noise	Right rear 5	5 mm	
Dashboard warning lights	Wheel bearings	Cooling System	Spare No	)	
Vipers (front & rear)	Wheel balance	Coolant condition	Tools		
Vindow winder FL	Brakes	Performance	Interior		
/indow winder FR	Performance	Radiator / Hoses (visual)	AC Operation		
/indow winder RL	Hand Brake		Heater fan		
/indow winder RR		Suspension	Seatbelts		
ear view mirrors	Keys & Locking	Suspension performance	Horn		
adio (basic test only)	Central locking	Steering performance			
D (basic test only)	Remote locking	Shock absorbers			
eversing camera	Number of keys	1 Inspected by: Kyle Mills-Brow			

Name: .....

Signature: .....