

Turners Certified Imports 50 Point Check

Report ID: 19,154,558

Version:

05 Apr 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	accredited inspection agency	and been test driven up	to 50km/n from co	ila.	
Make: Subaru Model: Impreza Odometer: 49,547 Kms Year: 2008 VIN: 7AT0GF09X19804509 Under Carriage & Under Bonnet Inspection Comments General Comments		Panels: Dashboard Engine Tim Evidence of	driver seat worn Average Average d: Average ning Mechanism: of Cam Belt Replacem At (odometer reading	Cambelt nent: No	
		Road Cond	ditions During Test Di	rive: Dry	
Electrical Transmission & Drive		ve Engine		Tyres (lowest ob depth)	served tread
Battery	Operation	Oil level		Left front	7 mm
Head lights	Noise	Smoke & fu	umes	Right front	6 mm
Tail lights	Clutch	• Performan	oce 🔽	Left rear	7 mm
Indicators	CV joints	Noise		Right rear	7 mm
Dashboard warning lights	s Wheel bearings	Cooling Sy	vstem	Spare	Yes
Wipers (front & rear)	Wheel balance	Coolant co		Tools	
Window winder FL	Brakes	Performan		Interior	
Window winder FR	Performance		Hoses (visual)	AC Operation	
Window winder RL		Radiator	Hoses (visual)		
Window winder RR	Hand Brake	Suspensio	on	Heater fan	
Rear view mirrors	Keys & Locking	Suspension	n performance	Seatbelts	
1				I Horn	

•

Central locking

Remote locking

Number of keys

Radio (basic test only)

CD (basic test only)

Reversing camera

1

Steering performance

Inspected by: Kyle Mills-Brown

Shock absorbers

Date: 05 Apr 2019

X = Fail = Not applicable for this vehicle

Turners Certified Key

✓ = Pass