

Turners Certified Imports 50 Point Check

Report ID: 19,157,521

Version:

30 May 2019 Created:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Seats:

Mazda Make: **Body Style: Hatchback** Demio Odometer: 98,243 Kms Model:

2010 7AT0C12HX19275888 VIN: Year:

Under Carriage & Under Bonnet Inspection Comments

Average Carpets: Average Panels: Dashboard: Average

front seats stained


General Comments


No spare tyre


Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading): Dry **Road Conditions During Test Drive:**

depth)

Electrical		
Battery		
Head lights		
Tail lights		
Indicators		
Dashboard warning lights		
Wipers (front & rear)		
Window winder FL		
Window winder FR		
Window winder RL		
Window winder RR	'	
Rear view mirrors	V	
Radio (basic test only)	'	
CD (basic test only)	'	
Reversing camera	•	







Tyres (lowest observed tread

Inspected by: John Lindsay Date: 11 Apr 2019

✓ = Pass

= Not applicable for this vehicle