

Turners Certified Imports 50 Point Check

Report ID: 19,157,702

Version:

Created: 11 Apr 2019

Date: 11 Apr 2019

Signature:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED diagno accredi	stic testing undertaken. The vehi ted inspection agency and been te	cle has undergone a thorough co st driven up to 50km/h from cold.	mpliance check by an NZTA
		Seats: Good Carpets: no floor mat Panels: Good Dashboard: Good	
General Comments		Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Timing Chain Not Applicable Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare N/A
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RR Window winder RR	Hand Brake	Suspension	Heater fan 🔽
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

1

Inspected by: Jason Law

Number of keys

Reversing camera