

Turners Certified Imports 50 Point Check

 Report ID:
 19,158,881

 Version:
 1

 Created:
 11 Apr 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Volkswagen	Body Style:	Hatchback
Model:	Polo1.6	Odometer:	50,681 Kms
Year:	2008	VIN:	WVWZZZ9NZ8U031187

Under Carriage & Under Bonnet Inspection Comments

Seats:	Average		
Carpets:	Average		
Panels:	Average		
Dashboard:	Average		
Engine Timing Mechanism:		Timing Chain	

Dry

General Comments

Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive:

			Road Conditions During Test Drive:					
Electrical		Transmission & Drive		Engine		Tyres (lowest observed tread depth)		
Battery		Operation		Oil level		Left front	7 mm	
Head lights		Noise		Smoke & fumes		Right front	7 mm	
Tail lights		Clutch		Performance		Left rear	7 mm	
Indicators		CV joints		Noise		Right rear	7 mm	
Dashboard warning lights		Wheel bearings		Cooling System		Spare	Yes	
Wipers (front & rear)		Wheel balance		Coolant condition		Tools		
Window winder FL		Brakes		Performance		Interior		
Window winder FR		Performance		Radiator / Hoses (visual)		AC Operation		
Window winder RL		Hand Brake				Heater fan		
Window winder RR				Suspension		Seatbelts		
Rear view mirrors		Keys & Locking		Suspension performance		Horn		
Radio (basic test only)		Central locking		Steering performance				
CD (basic test only)		Remote locking		Shock absorbers		Turners Certified H ✓ = Pass • = Not applicable	🗙 = Fail	
Reversing camera	•	Number of keys 1		Inspected by: John Lindsay			1 Apr 2019	

Name:

Signature: