

## Turners Certified Imports 50 Point Check

Report ID: 19,158,984

Version:

Created: 11 Apr 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED IMPORTED VEHICLES	diagnosti accredite	c testing undertaken. The dinspection agency and b	e vehicle has been test drive	undergone a n up to 50km/h	thorough co from cold.	mpliance check	by an NZTA	
Make: Volkswagen Body Style: Hatchback Model: Polo Odometer: 51,121 Kms Year: 2009 VIN: WVWZZZ9NZ9U023944  Under Carriage & Under Bonnet Inspection Comments 2WD  General Comments				Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism: Cambelt  Evidence of Cam Belt Replacement: No  Replaced At (odometer reading):  Road Conditions During Test Drive: Wet				
Electrical		Transmission & Drive	Engi	ine		<b>Tyres</b> (lowest observe)	erved tread	
Battery		Operation	Oil le	evel		Left front	7.0 mm	
Head lights		Noise	Smo	ke & fumes		Right front	7.0 mm	
Tail lights		Clutch	• Perfe	ormance		Left rear	7.0 mm	
Indicators		CV joints	Nois	e		Right rear	7.0 mm	
Dashboard warning lights		Wheel bearings	Coo	ling System		Spare	Yes	
Wipers (front & rear)		Wheel balance		lant condition		Tools		
Window winder FL		Brakes		ormance		Interior		
Window winder FR		Performance		ator / Hoses (visu	al)	AC Operation	<b>√</b>	
Window winder RL		Hand Brake			u., 🛡	Heater fan		
Window winder RR			Susp	pension	4	Seatbelts		
Rear view mirrors		Keys & Locking	Susp	pension performa	nce	Horn		
Radio (basic test only)		Central locking	Stee	ring performance		Turners Certified I	Key	

Remote locking

Number of keys

CD (basic test only)

Reversing camera

Inspected by: Ca Thach

2

Date: 11 Apr 2019

**X** = Fail = Not applicable for this vehicle