

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Honda	Body Style:	SUV
Model:	Stream	Odometer:	61,233 Kms
Year:	2008	VIN:	7AT08GADX19070039

Under Carriage & Under Bonnet Inspection Comments

Seats:	Average	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
Engine Timing Mechanism:		Timing Chain

Not Applicable

mm

mm

mm

mm

Wet

General Comments

Replaced At (odometer reading): **Road Conditions During Test Drive:**

Evidence of Cam Belt Replacement:

Tyres (lowest observed tread Electrical **Transmission & Drive** Engine depth) 7 Battery Operation Oil level Left front 6 **Head lights** Noise Smoke & fumes **Right front** 7 Tail lights Clutch Performance Left rear 7 Indicators **CV** joints Noise **Right rear** Dashboard warning lights Yes Wheel bearings Spare **Cooling System** Wipers (front & rear) Wheel balance Tools Coolant condition Window winder FL **Brakes** Interior Performance Window winder FR Radiator / Hoses (visual) Performance **AC Operation** Window winder RL Hand Brake Heater fan **Suspension** Window winder RR Seatbelts **Keys & Locking** Suspension performance Rear view mirrors Horn Radio (basic test only) **Central locking** Steering performance **Turners Certified Key** CD (basic test only) **Remote locking** Shock absorbers X = Fail = Pass = Not applicable for this vehicle • 1 **Reversing camera** Number of keys Inspected by: John Lindsay Date: 12 Apr 2019

Name:

Signature: