

Turners Certified Imports 50 Point Check

Report ID: 19,161,378

Version:

Created: 12 Apr 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold

IMPORTED VEHICLES	accredite	ed inspection agency and b	een test unven	up to 30km/m ii	om cola.			
Make: Mazda Body Style: Hatchback Model: Axela Odometer: 99,456 Kms Year: 2014 VIN: 7AT0C13JX19103508 Under Carriage & Under Bonnet Inspection Comments General Comments			Panels: Dashbo	Good		Timing Chain Not Applicable		
				ed At (odometer of the conditions During		Wet		
Electrical		Transmission & Drive	Engine	e		Tyres (lowest obsidepth)	erved tread	
Battery		Operation	Oil leve	el		Left front	5	mm
Head lights		Noise	Smoke	& fumes		Right front	5	mm
Tail lights		Clutch	• Perforr	nance		Left rear	4	mm
Indicators		CV joints	Noise			Right rear	4	mm
Dashboard warning light	s 🚺	Wheel bearings	Coolin	g System		Spare	N/A	
Wipers (front & rear)		Wheel balance		nt condition		Tools		
Window winder FL		Brakes	Perforn			Interior		
Window winder FR		Performance		or / Hoses (visual)		AC Operation		
Window winder RL Window winder RR		Hand Brake	Suspe			Heater fan		

CD (basic test only)

Reversing camera

Rear view mirrors

Radio (basic test only)

Noise	
Clutch	•
CV joints	
Wheel bearings	
Wheel balance	
Brakes	
Performance Hand Brake	✓
Keys & Locking	
Central locking	
Remote locking	
Number of keys	2

Smoke & fumes	Right front	5 mm
Performance	Left rear	4 mm
Noise	Right rear	4 mm
Cooling System	Spare	N/A
Coolant condition	Tools	
Performance	Interior	
Radiator / Hoses (visual)	AC Operation	
Suspension	Heater fan	
Suspension performance	Seatbelts	
Steering performance	Horn	
Shock absorbers	_	X = Fail

Inspected by: John Lindsay

Date: 12 Apr 2019