

Report ID: 19,162,871 Version: 1 Created: 15 Apr 2019

Make:	Ford	Model:	Mondeo	Body Style:	Sedan		Pass	Fail	N/A
Year:	2009	Registration:	KGC862	Reg Expiry:	11 Jun 2019	Engine			4
WoF Expiry:	02 Nov 2019	Odometer:	223,077 Kms	Good No:	19162871	Oil level	~		
VIN:	WF0DXXGBBD9B0214	Next Service:		Service Histor	y: No	Smoke & fumes	~		-
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		+
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	S P SC S SC	-161-	S PT SC	Radiator / Hoses (visual)	~		-
S = scratch						Transmission			
D = dent	S D SC			The	SD PT	Operation	~		1
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack				+	SC	Clutch	•		~
P = pin dent	Ho	KI			JUII —	CV joints	~		
* = decals	SPSC DE			J.	ELLAR S SC	,	-		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S SC W S D SC S SC W S SC						Brakes			
		Note or				Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		<u> </u>
Damage on rear bumper. Suntan lotion damage on paint. Stonechips on windscreen. Windscreen						Tyres (lowest observed tread depth of tyres)			es)
delaminating across top edge. No spare wheel retaining bolt.Wear on RF seat and seatbelt.lid on pocket in console not shutting. Wear on						Left front	4 mm		
	rols.Remote locking not				5	Right front	5	5	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	4	1	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension	1			
Wear in rea bumper lov	r suspension bushes. Er ver lin	ngine splash gua	rd is damaged and not	secure. Damage	under front	Suspension performance	~		
bumperior						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories	-		
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		1
						Window winder FR	~		
General Comments					Window winder RL	~			
Rubber boot on aerial mount is damaged.					Window winder RR	~			
Drives ok .						Rear view mirrors	~		1
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	~		T
						Remote locking		~	+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						Ĺ	1		
Inspected by: Roger King Date: 15 Apr 2019									
I have read a	and understood th	is condition c	uide. Name: .			Signature:			