

Turners Certified Imports 50 Point Check

Report ID: 19,163,188

Version:

Created: 13 May 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED diagnot accred	ostic testing undertaken. The veh lited inspection agency and been to	icle has undergone a thorough co est driven up to 50km/h from cold.	mpliance check by an NZTA
Model: Stream O	ody Style: SUV dometer: 97,880 Kms IN: 7AT08GADX19073488 et Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading):	Timing Chain Not Applicable Dry
Electrical	Transmission & Drive	Road Conditions During Test Drive: Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7.0 mm
Head lights	Noise	Smoke & fumes	Right front 7.0 mm
Tail lights	Clutch	Performance	Left rear 7.0 mm
Indicators	CV joints	Noise	Right rear 7.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan 🗸
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	Tumpus Coutified Vo.
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

Inspected by: Mathew Varghese

Date: 16 Apr 2019

Signature:

Number of keys

Name:

Reversing camera