

Turners Certified Imports 50 Point Check

Report ID: 19,165,303 Version: 1 Created: 18 Apr 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Subaru	Body Style:	Hatchback
Model:	Impreza	Odometer:	81,985 Kms
Year:	2010	VIN:	7AT0GF09X19041337

Under Carriage & Under Bonnet Inspection Comments 2WD

Engine Timii	ng Mechanism:	Cambelt
Dashboard:	Good	
Panels:	Good	
Carpets:	Good	
Seats:	Good	

General Comments

Dashboard: Good		
Engine Timing Mechanism:	Cambelt	
Evidence of Cam Belt Replacement:	No	
Replaced At (odometer reading):		

Dry Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation 🖌	Oil level	Left front 3.0 mm
Head lights	Noise	Smoke & fumes	Right front 4.0 mm
Tail lights	Clutch	Performance	Left rear 3.0 mm
Indicators	CV joints	Noise	Right rear 3.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance		Tools
Window winder FL	Brakes	Coolant condition	Interior
Window winder FR	Diakes	Performance	
Window winder RL	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
			Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	 Turners Certified Key ✓ = Pass X = Fail ● = Not applicable for this vehicle
Reversing camera •	Number of keys 2	Inspected by: Mathew Varghese	Date: 17 Apr 2019

Name: