

## **Basic Vehicle Condition Guide**

Report ID: 19,271,053

Pass

1

/

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

**Transmission** 

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

**Hand Brake** 

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 03 Dec 2019

Fail

N/A

1

mm

mm

mm

 $\mathsf{mm}$ 

6

6

1

/

/

/

1

1


2

Yes

Make: Model: Holden Colorado **Body Style:** Utility Year: 2014 Registration: HKQ873 **Reg Expiry:** 30 Nov 2019 WoF Expiry: **Odometer:** 11 Nov 2020 153,062 Kms **Good No:** 19271053 VIN: MMU148MK0EH6292<sup>2</sup> Next Service: 160000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Minor stone chips in the windscreen,

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	one of the ignition keys doesn't open stuck ,		

## **General Comments**

**Road Conditions During Test Drive:** Dry

	Remote locking	<b>'</b>		
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)		~	
Evidence of Cam Belt Replacement: Yes	Kms: 151,193	Reversing camera	~	
Inspected by: Donovan Matara	Date: 03 Dec 2019			
have read and understood this condition guide.	Name: Signa			