

## **Basic Vehicle Condition Guide**

Report ID: 1,220 Version: 3

Engine

Oil level

Created: 05 Aug 2019


Fail

N/A

Make: Model: Peugeot 308 **Body Style:** Hatchback Year: 2008 Registration: JDC619 Reg Expiry: 10 Nov 2019 **WoF Expiry: Odometer: Good No:** 28 May 2020 152,830 Kms 19469453 VIN: VF34CRHRJ55025628 **Next Service:** 162840 **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments	<u>5</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

## **General Comments**

A/C not cold

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

V							
~							
~							
~							
~							
~							
•	•	•					
~							
~							
		~					
~							
~							
~							
~							
Tyres (lowest observed tread depth of tyres)							
7	7.0	mm					
7	7.0	mm					
7.0		mm					
1 4							
	5.0	mm					
		mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
\( \times \)	5.0	mm					
\( \times \)	5.0	mm					
\( \times \)	5.0	mm					
V V V V V V V V V V V V V V V V V V V	5.0	mm					
\( \times \)	5.0	mm					
V V V V V V V V V V V V V V V V V V V	5.0	mm					
ン ン ン ン ン ン ン ン ン ン ン ン ン ン	5.0	mm					
V V V V V V V V V V V V V V V V V V V	5.0	mm					
V V V V V V V V V V V V V V V V V V V	5.0	mm					
	5.0	mm					
	5.0	mm					
	5.0	mm					
		7.0					

I have read and understood this condition guide.

Name <sup>,</sup>			

07 May 2019

Reversing camera