

## **Turners Certified Imports 50 Point Check**

Report ID: 19,472,660

Version:

29 Apr 2019 Created:

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Suzuki **Body Style: Hatchback** Splash Odometer: 54,619 Kms Model: TSMEXB32S00166699 2008 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** 

**General Comments** 


driver seat worn, all seats marks Seats: Average Carpets: Average Panels: Dashboard: Average


Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading):


**Road Conditions During Test Drive:** 

Dry

Electrical	
Battery	<b>V</b>
Head lights	
Tail lights	
Indicators	
Dashboard warning lights	
Wipers (front & rear)	
Window winder FL	
Window winder FR	
Window winder RL	
Window winder RR	
Rear view mirrors	
Radio (basic test only)	
CD (basic test only)	
Reversing camera	•







**Tyres** (lowest observed tread

Inspected by: Kyle Mills-Brown Date: 29 Apr 2019
--