

Turners Certified Imports 50 Point Check

Report ID: 19,473,147 Version: 1 Created: 21 May 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Volkswagen	Body Style: Hatchback
Model:	Polo	Odometer: 60,121 Kms
Year:	2008	VIN: WVWZZZ9NZ8U006195

Under Carriage & Under Bonnet Inspection Comments

Seats:	Drivers seat worn
Carpets:	Average
Panels:	Average
Dashboard:	Cup holder broken
	Cambolt

General Comments

	Panels: Proceede	
	Dashboard: Cup holder broken	
	Engine Timing Mechanism:	Cambelt
	5 5	
	Evidence of Cam Belt Replacement	: No
	Replaced At (odometer reading):	
	Road Conditions During Test Drive	Dry

Electrical		Transmission & Drive		Engine		Tyres (lowest observed tread depth)		
Battery		Operation		Oil level		Left front	7	mm
Head lights		Noise		Smoke & fumes		Right front	7	mm
Tail lights		Clutch	•	Performance		Left rear	7	mm
Indicators		CV joints		Noise		Right rear	7	mm
Dashboard warning lights		Wheel bearings		Cooling System		Spare	Yes	
Wipers (front & rear)		Wheel balance				Tools		I
Window winder FL		Brakes		Coolant condition		Interior		
Window winder FR				Performance			_	
Window winder RL	~	Performance		Radiator / Hoses (visual)		AC Operation	V	
Window winder RR		Hand Brake		Suspension		Heater fan	V	
Rear view mirrors		Keys & Locking		Suspension performance		Seatbelts		
						Horn		
Radio (basic test only)		Central locking		Steering performance				
CD (basic test only)		Remote locking		Shock absorbers		Turners Certified✔₽Pass●=Not applical	🗙 = Fail	hicle
Reversing camera	•	Number of keys	1	Inspected by: Kyle Mills-E	Brown	Date: 2	1 May 2019	

Signature: