

## **Turners Certified Imports 50 Point Check**

Report ID: 19,476,248

Version:

07 May 2019 Created:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Honda Make: **Body Style: Hatchback** FIT Odometer: 96,604 Kms Model: 2014 7AT08G2YX19020449 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** 

2WD

**General Comments** 

Good Seats: Good Carpets: Good Panels: Dashboard: Good

Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** 

**Road Conditions During Test Drive:** 

Replaced At (odometer reading):

Dry

**Electrical Battery Head lights** Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Reversing camera •





