

## **Turners Certified Imports 50 Point Check**

Report ID: 19,481,130 Version: 1 Created: 08 May 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Mitsubishi	Body Style:	
Model:	Outlander	Odometer:	70,830 Kms
Year:	2016	VIN:	7AT0CJ3MX19003901

Under Carriage & Under Bonnet Inspection Comments 4WD

	Seats:	Good	
	Carpets:	Good	
	Panels:	Good	
	Dashboard:	Good	
	Engine Timii	ng Mechanism:	Timing Chain
	Evidence of	Cam Belt Replacement:	Not Applicable

**General Comments** 

Evidence of Cam Belt Replacement: Replaced At (odometer reading): Dry

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest ob depth)	<b>Tyres</b> (lowest observed tread depth)	
Battery	Operation	Oil level	Left front	8.0 m	
lead lights	Noise	Smoke & fumes	Right front	8.0 m	
il lights	Clutch	Performance	Left rear	8.0 m	
dicators	CV joints	Noise	Right rear	8.0 m	
ashboard warning lights 🚺	Wheel bearings	Cooling System	Spare	N/A	
lipers (front & rear)	Wheel balance	Coolant condition	Tools		
indow winder FL	Brakes	Performance	Interior		
indow winder FR	Performance	Radiator / Hoses (visual)	AC Operation	V	
indow winder RL	Hand Brake		Heater fan	V	
indow winder RR		Suspension	Seatbelts	V	
ear view mirrors	Keys & Locking	Suspension performance	Horn		
adio (basic test only)	Central locking	Steering performance			
D (basic test only)	Remote locking	Shock absorbers	Turners Certifie ✓ = Pass ● = Not applic	<b>d Key</b> <b>X</b> = Fail cable for this vehic	
eversing camera	Number of keys 2	Inspected by: Ca Thach		07 May 2019	

Name: .....

Signature: .....