

Turners Certified Imports 50 Point Check

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Volkswagen	Body Style:	Hatchback
Model:	Polo1.6	Odometer:	40,671 Kms
Year:	2009	VIN:	WVWZZZ9NZ9U015513

Under Carriage & Under Bonnet Inspection Comments

Seats:	Average	
Carpets:	driver mat worn	
Panels:	Average	
Dashboard:	Average	
Engine Timir	ng Mechanism:	Timing Chain

Dry

General Comments

Dashboard: Average	
Engine Timing Mechanism:	Timing Chain
Evidence of Cam Belt Replacement:	Not Applicable
Replaced At (odometer reading):	

Road Conditions During Test Drive:

Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 7 mm
Head lights	Noise	Smoke & fumes	Right front 7 mm
Tail lights	Clutch	Performance	Left rear 7 mm
Indicators	CV joints	Noise	Right rear 7 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance		Tools
Window winder FL	Brakes	Coolant condition	Interior
Window winder FR		Performance	
Window winder RL	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RR	Hand Brake	Suspension	Heater fan
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✔= Pass¥= Fail●= Not applicable for this vehicle
Reversing camera •	Number of keys 2	Inspected by: John Lindsay	Date: 29 May 2019

Signature: