

## Turners Certified Imports 50 Point Check

Report ID: 19,484,797

Version:

Signature: .....

Created: 14 May 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

IMPORTED VEHICLES	accredite	d inspection agency a	and been tes	t driven up to 50l	km/h from cold.			
Make: Body Style:  Model: Odometer: 119,617 Kms  Year: VIN: 7AT0C144X19140703  Under Carriage & Under Bonnet Inspection Comments 2WD				Seats: Good  Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism: Timing Chain				
General Comments				Evidence of Cam Replaced At (odd	Belt Replacement:	Not Applicable	,	
Electrical		Transmission & Drive	e	Engine		<b>Tyres</b> (lowest observed)	erved tread	
Battery		Operation		Oil level		Left front	6.0	mm
Head lights		Noise		Smoke & fumes		Right front	6.0	mm
Tail lights		Clutch	•	Performance		Left rear	4.0	mm
Indicators		CV joints		Noise		Right rear	4.0	mm
Dashboard warning light	s 🚺	Wheel bearings		Cooling System		Spare	N/A	
Wipers (front & rear)		Wheel balance		Coolant conditio		Tools		
Window winder FL		Brakes		Performance		Interior		
Window winder FR		Performance		Radiator / Hoses	(vicual)	AC Operation	ſ	
Window winder RL		Hand Brake		nadiator / noses	(Visual)	Heater fan		
Window winder RR		напо втаке		Suspension		Seatbelts		
Rear view mirrors		Keys & Locking		Suspension perfo	ormance			
Radio (basic test only)		Central locking		Steering perform	nance	Horn		
CD (basic test only)		Remote locking		Shock absorbers		Turners Certified I  ✓ = Pass  • = Not applical	<b>X</b> = Fail	ehicle
Reversing camera		Number of keys	2	Inspected by: Ma	athew Varghese		3 May 2019	

Name: .....