

## **Turners Certified Imports 50 Point Check**

Report ID: 19,499,539

Version:

24 May 2019 Created:

## **Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Mazda Make: **Body Style: Hatchback** Axela Odometer: 51,096 Kms Model: 7AT0C13JX19220139 2006 VIN: Year:

**Under Carriage & Under Bonnet Inspection Comments** 


**General Comments** 


Good Seats: Good Carpets: Good Panels: Dashboard: Good


Timing Chain **Engine Timing Mechanism:** Not Applicable **Evidence of Cam Belt Replacement:** Replaced At (odometer reading):

Dry **Road Conditions During Test Drive:** 

Electrical
Battery
Head lights
Tail lights
Indicators
Dashboard warning lights
Wipers (front & rear)
Window winder FL
Window winder FR
Window winder RL
Window winder RR
Rear view mirrors
Radio (basic test only)
CD (basic test only)







Reversing camera