

## Turners Certified Imports 50 Point Check

 Report ID:
 19,499,933

 Version:
 1

 Created:
 27 May 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make:	Toyota	Body Style:	Hatchback
Model:	Corolla	Odometer:	94,887 Kms
Year:	2008	VIN:	7AT0H667X19041418

Under Carriage & Under Bonnet Inspection Comments

## General Comments

Front wheel drive

Seats:	Good	
Carpets:	Good	
Panels:	Good	
Dashboard:	Good	
Engine Timir	ng Mechanism:	Timing Chain
Evidence of Cam Belt Replacement:		Not Applicable

Wet

Road Conditions During Test Drive:

Replaced At (odometer reading):

Electrical	Transmission & Drive	Engine	<b>Tyres</b> (lowest observed tread depth)	
Battery	Operation	Oil level	Left front <b>7</b> mm	
Head lights	Noise	Smoke & fumes	Right front <b>7</b> mm	
Tail lights	Clutch	Performance	Left rear 7 mm	
Indicators	CV joints	Noise	Right rear <b>7</b> mm	
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes	
Wipers (front & rear)	Wheel balance	Coolant condition	Tools	
Window winder FL	Brakes	Performance	Interior	
Window winder FR	Performance	Radiator / Hoses (visual)		
Window winder RL	Hand Brake		AC Operation	
Window winder RR	· · · · · · · · · · · · · · · · · · ·	Suspension	Seatbelts	
Rear view mirrors	Keys & Locking	Suspension performance		
Radio (basic test only)	Central locking	Steering performance	Horn	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key✓= PassX= Fail●= Not applicable for this vehicle	
Reversing camera	Number of keys 2	Inspected by: Xinghui Lin	Date: 27 May 2019	

Name: .....