

Turners Certified Imports 50 Point Check

Report ID: 19,501,195

Date: 28 May 2019

Signature:

Version:

Created: 30 May 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED diagnot accred	ostic testing undertaken. The vehi lited inspection agency and been te	icle has undergone a thorough coest driven up to 50km/h from cold.	ompliance check by an NZTA
Model: Golf	ody Style: Odometer: 94,502 Kms IN: WVWZZZ1KZ9U012004 Set Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good	
General Comments		Engine Timing Mechanism: Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Timing Chain Not Applicable Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 4.0 mm
Head lights	Noise	Smoke & fumes	Right front 4.0 mm
Tail lights	Clutch	Performance	Left rear 4.0 mm
Indicators	CV joints	Noise	Right rear 4.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL Window winder FR	Brakes	Performance	Interior
	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL Window winder RR	Hand Brake	Suspension	Heater fan 🗾
Rear view mirrors	Keys & Locking	Suspension performance	Seatbelts
Radio (basic test only)	Central locking	Steering performance	Horn
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

1

Inspected by: Xinghui Lin

Number of keys

Reversing camera