

## Turners Certified Imports 50 Point Check

Report ID: 19,503,095

Version:

Created: 31 May 2019

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA

IMPORTED VEHICLES	edited inspection agency and be	een test driven up to 50km/h from cold.	·		
Make: Mazda Body Style: SUV Model: CX-5 Odometer: 106,989 Kms Year: 2014 VIN: 7AT0C144X19134189  Under Carriage & Under Bonnet Inspection Comments Front wheel drive  General Comments		Panels: Good  Dashboard: Good  Engine Timing Mechanism:  Evidence of Cam Belt Replacement:  Replaced At (odometer reading):	Carpets: Good  Panels: Good  Dashboard: Good  Engine Timing Mechanism: Timing Chain  Evidence of Cam Belt Replacement: Not Applicable		
Electrical	Transmission & Drive	Engine	Tyres (lowest observ	ved tread	
Battery	Operation	Oil level	depth)  Left front	4.5 mm	
Head lights	Noise	Smoke & fumes	Right front	4.5 mm	
Tail lights	Clutch	Performance	Left rear	5.0 mm	
Indicators	CV joints	Noise	Right rear	5.0 mm	
Dashboard warning lights	Wheel bearings	Cooling System	Spare	N/A	
Wipers (front & rear)	Wheel balance	Coolant condition	Tools		
Window winder FL	Brakes	Performance	Interior		
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation		
Window winder RL	Hand Brake		Heater fan		
Window winder RR		Suspension	Seatbelts		
Rear view mirrors	Keys & Locking	Suspension performance	Horn		
Radio (basic test only)	Central locking	Steering performance			

•

Remote locking

Number of keys

CD (basic test only)

Reversing camera

2

**Shock absorbers** 

Inspected by: Ca Thach

Date: 28 May 2019

**X** = Fail = Not applicable for this vehicle

**Turners Certified Key** 

✓ = Pass