

Turners Certified Imports 50 Point Check

Report ID: 19,504,659

Date: 29 May 2019

Signature:

Version:

Created: 29 May 2019

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or

CERTIFIED diameter with the control of the control	gnostic testing undertaken. The veh redited inspection agency and been to	icle has undergone a thorough colest driven up to 50km/h from cold.	mpliance check by an NZTA
Make: Suzuki Model: Escudo Year: 2007 Under Carriage & Under Bo	Body Style: SUV Odometer: 63,599 Kms VIN: 7AT0GK4MX19200938 Innet Inspection Comments	Seats: Good Carpets: Good Panels: Good Dashboard: Good Engine Timing Mechanism:	Timing Chain
General Comments		Evidence of Cam Belt Replacement: Replaced At (odometer reading): Road Conditions During Test Drive:	Not Applicable Wet
Electrical	Transmission & Drive	Engine	Tyres (lowest observed tread depth)
Battery	Operation	Oil level	Left front 5.5 mm
Head lights	Noise	Smoke & fumes	Right front 5.5 mm
Tail lights	Clutch	Performance	Left rear 8.0 mm
Indicators	CV joints	Noise	Right rear 8.0 mm
Dashboard warning lights	Wheel bearings	Cooling System	Spare Yes
Wipers (front & rear)	Wheel balance	Coolant condition	Tools
Window winder FL	Brakes	Performance	Interior
Window winder FR	Performance	Radiator / Hoses (visual)	AC Operation
Window winder RL	Hand Brake		Heater fan 🔽
Window winder RR		Suspension	Seatbelts
Rear view mirrors	Keys & Locking	Suspension performance	Horn
Radio (basic test only)	Central locking	Steering performance	
CD (basic test only)	Remote locking	Shock absorbers	Turners Certified Key ✓ = Pass X = Fail • = Not applicable for this vehicle

Inspected by: Ca Thach

Number of keys

Reversing camera