

Report ID: 19,599,299 Version: 1 10 Jul 2019 Created:

Year: 2005 Registration: CLE677 Reg Expiry: 19 Sep 2019 WoF Expiry: 19 Jun 2020 Odometer: 160,137 Kms Good No: 19599299 VIN: KMHJN81BR5U09382: Next Service: 168000 Service History: No Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. Spector SPSC Coolant condition ✓ Coolant condition Key: SSC W SD SSC SP SC Performance ✓ Image: Coolant condition ✓ </th <th>Make:</th> <th>Hyundai</th> <th>Model:</th> <th>Tucson</th> <th>Body Style:</th> <th>SUV</th> <th></th> <th>Pass</th> <th>Fail</th> <th>N/A</th>	Make:	Hyundai	Model:	Tucson	Body Style:	SUV		Pass	Fail	N/A
Were Explore 19.0.1.020 Odometer: 19.0.127.Km: God NE: 19.999299 With: With With BRUDUSSI: Next Service: God NE: 19.999299 Methods (BruDUSSI: Next Service: God NE: Service History: No. Source House Service History: No. Service History: No. No. <td>Year:</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Engine</td> <td></td> <td></td> <td></td>	Year:						Engine			
VIN Meter Baragenitia not a warranty Service History Note Neter Baragenitia not a warranty Since & Administration Since & Administration Neter Baragenitia not a warranty Since & Administration Performance V Neter Baragenitia not a warranty Since & Administration Performance V Neter Baragenitia not a warranty Since & Administration Performance V Neter Baragenitia not a warranty Since & Administration Performance V Noter Construction Since & Administration Performance V Interformance Noter Construction Since & Administration V Interformance V Interformanc					• • •		5	~		
Net: This report is a guide only. Consideration is made for age and mileage. Parts have not been dismanted or global disposits cetting outdrakes. The vehicle may be 50km/h from cold. The Vendor recommendation of the center of the center of the vehicle commendation of the center of the center of the vehicle commendation of the center of the cent of the center of the center of the center of										
Note: This report is quide rules only consideration is made for age and mileage. Parts have not been diamanted of diagnosit cesting underlaker, the vehicle has been diamanted of additional charge. Note: Image: Constrained of the constrai								-		
Integration control to purchase and this can be arranged for an additional charge. Control to purchase and this can be arranged for an additional charge. Key: SSC No SSC S statutical inspection prior to purchase and this can be arranged for an additional charge. SSC No P = pin dent SSC SSC No SSC S = statutical inspection prior to purchase and this can be arranged for an additional charge. SSC No P = pin dent SSC SSC No SSC S = statutical inspection prior to purchase and this can be arranged for an additional charge. No Performance No S = statutical inspection comments SSC SSC No No Performance No Rev report on Statutical inspection comments Note some defects & bencharder inspin there mains on the displayed in the diagram. Performance No Performance No Performance No Performance No No Performance No No Performance No No No Performance No				с I II	D			•		
a full mechanical inspection prior to purchase and this can be ananged for an additional charge. Continition Inspection In								•		
Key: SS W SD SS W Image: SS SS W Image: SS SS </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>1</td>										1
Key: SSC W SS SSC W SS SSC W SSC SSC W SSC W W SSC SSC W SSC SSC SSC SSC SSC SSC			_					-		
S - startch Defent R - rust SSC P = paint defect SSC C - crack P = print defect S = start defect S = store chips Body Inspection Comments Note: some defects & blemishes may not be displayed in the dispray Body Inspection Comments Note: some defects & blemishes may not be displayed in the dispray Rear vige not sub parking. Headiamps need buffing. Dent in taligate. Charage on Bf door. IF grab handle in cof has tape on EL Hi sunvisor mount loose. Interior light less missing. Miror switch oft working properly. Heater vents not changing. AC not cold. All seats have weardamage. Under Carriage & Under Bonnet Inspection: Dry Under Carriage & Under Bonnet Inspection Comments Sugersion Coolant additive concentration below manufactures recomended level suggest colant change. LHF inner as a sub seepage. Front sweybar bushes worn. Some nust on rear of LH sill lower seam. Steering performance V Steering performance V Steering performance V Steering performance V Steering performance	Key:	S SC W	-0	S D S SC		S P SC		-		
D - dent SSC Per rotat PT - pain dent SPSC C - cack Per pin dent = decaits SPSC SC = store chips SPSC More is pain from scrifts SPSC SC = store chips Note: some defects & blenishes may not be displayed in the diagram Rear wige not self parking, Headiamps need buffing. Dent in taligate. Damage on R door. Performance Left root Tyres illowers observed troad depth of tyres) Left root 3 Working properly. Heater vents not changing. AC not cold. All seats have weard amage. Tyres illowers observed troad depth of tyres) Under Carriage & Under Bonnet inspection Comments Suspension performance Ves Social additive concentration Bonet inspection Comments Suspension performance Suspension performance Seats Poor Suspension performance Ves Soucehol additive concentration Bonet inspection Comments Suspension performance Ves Seats Poor Suspension performance Ves Dashboard Average Ves Suspension performance Ves Bashboard Average Ves Ves Sundenining windscreen ti	S = scratch	Se	A CO		10c	X	. , ,	V		
Notice ····································	D = dent	ISSC ALE			1 - L	EID S				1
C crack C intch Image: Construction of the second of	R = rust				10			-		
P = pin dent 55 C V V = dcails 55 C SD RF S = store chysis W = significant suffs V V Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram in orb has top end buffing. Dent in alighate. Damage on RF door. Hand Brake V Lis grab handlin in orb has top end buffing. Dent in alighate. Damage on RF door. Under Carriage & Under Bonnet Inspection Comments There will be an inspection comments Conditions During Body Inspection: Dry Dry Bight frant S mm Under Carriage & Under Bonnet Inspection Comments Supersion performance V Supersion Coolant additive concentration below manufactures recomended level suggest coolant change. Life inner and saborobers V Supersion Seats Poor Steering performance V Supersion Grapets Average V Supersion Supersion formance V Bashboard Average V Supersion formance	•	ect M			+	S P SC		~		
+ - decals SP SC - store chips W = significant souff SP W = souff Sport Sport S SP Had Sport SP Had Spo		Ho								
SC = stone chips W = significant scuffs P P Body Inspection Comments Note: some defects & biemshes may not be displayed in the diagram Parafe Rear wijper not self parking. Headamps need buffing. Dent in tailgate. Damage on RF door. Tyree flowest observed tread depth of tyres) Left from 3 mm Rear wijper not self parking. Headamps need buffing. Dent in tailgate. Damage on RF door. Tyree flowest observed tread depth of tyres) Left from 3 mm Rear wijper not self parking. Headamps need buffing. Dent in tailgate. Damage on RF door. Left fromt 3 mm Left fromt 5 mm Right front 5 mm Road Conditions During Body Inspection: Dry Supersion Supersion Supersion Coolant additive concentration below manufactures recomended level suggest coolant change. LHF inner aske seal has oil seepage. Front swaybar bushes worn. Some rust on rear of LH sill lower sean. Supersion Supersion Supersion Interior Comments Seats Poor Indicatos Indic	•	SPSC DC				ALA SDRP		-		
W = significant scutt SP W S SDP Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram my property, Heater vents not changing. Act not cold. All seats have wear/damage. Performance V Under Carriage & Under Bonnet Inspection Comments 0 0 mm Conditions During Body Inspection: Dry Prov 1 mm Under Carriage & Under Bonnet Inspection Comments Soper Yes Conditions During Body Inspection: Dry Note: some networking. Performance V 1 Interior Comments Seats Poor Supersion Supersion Supersion Seats Poor Verage V 1 Supersion V 1 Panels Poor Indicions Average V 1 Supersion V 1 Restabelt nor textcring. Both reard door cards have damage. Tailgate rubber damaged. Rust in tailgate. Some diversion V 1 1 1 1 Bashboard Average Indicions During Test Drive: Dry Indicions V 1 1 1 1 1 1 1 1 1 1 </td <td>SC = stone chi</td> <td>ps U</td> <td></td> <td></td> <td>10</td> <td></td> <td></td> <td>~</td> <td></td> <td></td>	SC = stone chi	ps U			10			~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram Rear wiper not self parking, Headlamps need buffing. Dent in tailgate. Damage on RF door. If and Brake V LE grab handle in roof has tape on it. LH sunvisor mount loose. Interior light lens missing. Mirror switch not working properly. Heater vents not changing. AC not cold. All seats have wear/damage. If the displayed in the diagram Conditions During Body Inspection: Dry Night front 3 mm Under Carriage & Under Bonnet Inspection Comments Spare Yes Suspension Coolant additive concentration below manufactures recomended level suggest coolant change. LHF inner axle seal has oil seepage. Front swaybar bushes worn. Some rust on rear of LH sill lower seam. Spare Yes Interior Comments Seats Poor Steering performance V Image in the dilights Image in the dilights V Image in the dilights V Image in the dilights V Image in the dilights Image in the dilights V Image in the dilights	W = significan	t scuffs	$-\omega$	IS IC						1
Dody inspection Fyres (lowest observed tread depth of tyres) Rear wipe not soft parking, Headamps need buffing. Dent in tailgate. Damage on RF door. Fyres (lowest observed tread depth of tyres) Lef grab handle in roof has tape on it. LH survisor mount loose. Interior light lens missing, Mirror switch not working properly. Heater vents not changing. AC not cold. All seats have wear/damage. I Conditions During Body Inspection: Dry Right front 5 mm Under Carriage & Under Bonnet Inspection Comments Suspension performance ✓ 1 Coolent additive concentration below manufactures recomended level suggest coolant change. LHF inner axle seal has oil seepage. Front swaybar bushes wom. Some rust on rear of LH sill lower seam. Suspension performance ✓ 1 Seats Poor Stock absorbers ✓ 1 1 Panels Poor Seats ✓ 1 1 Dashboard Average ✓ 1 1 1 1 Breadet not retracting. Both rear door cards have damage. Tailgate rubber damaged. Rust in tailgate. Stonechips on windscreen. Tape holding windscreen trim on RH A pillar. CD player not working. Remote locking on windsreen. Tape holding windscreen trim on RH A pillar. CD player not working. Remote locking ✓ 1 Drives ok. Central locking ✓		JP W								
Index of marker in advise in advising here bolding, before many took. Intervol light lens missing. Mirror switch net working properly. Heater vents not changing. AC not cold. All seats have wear/damage. I Left front 3 mm Interview in roof has tape on it. LH's summer many tooks. Interview in the roof light lens missing. Mirror switch net working properly. Heater vents not changing. AC not cold. All seats have wear/damage. I Left front 3 mm Right front 5 mm Right front 5 mm Right front 5 mm Right rear 5 mm Right rear 5 mm Right rear 5 mm Right rear 5 mm Spare Yes Spare Yes Suspension performance ✓ 1 2 Steering performance ✓ 1 2 Interior Comments Seats Poor 1 1 Bashboard Average 1 1 1 Dashboard Average 1 1 1 Drives ok. Co ladding before many fragge reade working. Remote locking on windscreen. Tape holding windscreen trim on RH A pillar. CD player not working. Remote	Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram		-		Ļ
working properly. Heater vents not changing. AC not cold. All seats have wear/damage. Right front 5 mm Right front 5 mm Conditions During Body Inspection: Dry Right front 5 mm Under Carriage & Under Bonnet Inspection Comments Suspension Suspension Suspension 1 <							•	d depth	of tyre	3S)
Right front 5 mm Conditions During Body Inspection: Dry Interar 5 mm Under Carriage & Under Bonnet Inspection Comments Sapare Yes Coolant additive concentration below manufactures recomended level suggest coolant change. LHF inner axle seal has oil seepage. Front swaybar bushes worn. Some rust on rear of LH sill lower seam. Suspension performance ✓						Airror switch not			3	mm
Conditions During Body Inspection: Dry Right rear 5 mm Under Carriage & Under Bonnet Inspection Comments Suspension Suspension Suspension performance ✓ Coolant additive concentration below manufactures recomended level suggest coolant change. LHF inner arkies eail has oil seepage. Front swaybar bushes worn. Some rust on rear of LH sill lower seam. Suspension performance ✓ <td< td=""><td>51</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>5</td><td>mm</td></td<>	51								5	mm
Under Carriage & Under Bonnet Inspection Comments Spare Yes Colant additive concentration below manufactures recomended level suggest coolant change. LHF inner axide seal has oil seepage. Front swaybar bushes worn. Some rust on rear of LH sill lower seam. Suspension performance ✓							Left rear	·	4	mm
Under Carriage & Under Bonnet Inspection Comments Suspension Coolant additive concentration below manufactures recomended level suggest coolant change. LHF inner axle seal has oil seepage. Front swaybar bushes worn. Some rust on rear of LH sill lower seam. Suspension performance ✓ I Suspension performance ✓ I Interior Comments Suspension performance ✓ I Interior Comments Seats Poor Indicators ✓ I Carpets Average Indicators ✓ I I Dashboard Average Indicators ✓ I I Is seatable not retracting. Both rear door cards have damage. Tailgate rubber damaged. Rust in tailgate. Stonechips on windscreen. Tape holding windscreen trim on RH A pillar. CD player not working. Remote locking not working. ✓ I I Drives ok. Central locking ✓ I I I Road Conditions During Test Drive: Dry I I I I Remote locking ✓ I I I I Indicators ✓ I I I I I Dashboard Average ✓ I	Conditions During Body Inspection: Dry						Right rear	:	5	mm
Coolant additive concentration below manufactures recomended level suggest coolant change. LHF inner axle seal has oil seepage. Front swaybar bushes worn. Some rust on rear of LH sill lower seam. Sugension performance ✓ I Sugension performance ✓ I Steering performance ✓ I Interior Comments ✓ ✓ I				C			Spare Yes			
axle seal has oil seepage. Front swaybar bushes worn. Some rust on rear of LH sill lower seam. Interview of the second secon		-					· ·		1	
Steering performance ✓							Suspension performance	~		
Interior Comments Air Conditioning / Heater Seats Poor Electrical / Accessories Carpets Average Indicators ✓ I Panels Poor Indicators ✓ I Dashboard Average Indicators ✓ I Its eatbelt not retracting. Both rear door cards have damage. Tailgate rubber damaged. Rust in tailgate. Stonechips on windscreen trim on RH A pillar. CD player not working. Remote locking not working. ✓ I ✓ I Drives ok. Indicots test only) ✓ I I I Read Conditions During Test Drive: Dry Instructional (basic test only) ✓ I I Engine Timing Mechanism: Cambelt Eversing camera ✓ I I Engine Timing Mechanism: Yes Kms: 137,512 Sat. Nav. (basic test only) I I		son seepage. Hone swe	iyour busiles wo	in. Some rust on real e	in Err Sin lower set		Steering performance	~		
Interior CommentsOperationISeatsPoorICarpetsAverageIPanelsPoorIndicatorsIDashboardAverageIDashboardAverageILR seatbelt not retracting. Both rear door cards have damage. Tailgate rubber damaged. Rust in tailgate. Icking not working.Vindow winder FRIDrives ok.IIRoad Conditions During Test Drive:DryCentral lockingVEngine Timing Mechanism:Cambelt Evidence of Cam Belt Replacement:YesKms:YesKms:137,512Sat. Nav. (basic test only)VReversing cameraVIVReversing cameraVIVSat. Nav. (basic test only)VVSet restroling cameraVIIndications Cambelt Evidence of Cam Belt Replacement:YesKms:YesKms:137,512Sat. Nav. (basic test only)VReversing cameraVIVReversing cameraVIVReversing cameraVIVReversing cameraVIVSat. Nav. (basic test only)VVReversing cameraVISat. Nav. (basic test only)VVReversing cameraVISat. Nav. (basic test only)VReversing cameraVISat. Nav. (basic test only)VReversing cameraVV <t< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td>Shock absorbers</td><td>~</td><td></td><td></td></t<>							Shock absorbers	~		
Interior Comments Poor Seats Poor Carpets Average Panels Poor Dashboard Average Dashboard Average Mathematical Comments Indicators Image Dashboard Average Mathematical Comments Image Image LR seatbelt not retracting. Both rear door cards have damage. Tailgate rubber damaged. Rust in tailgate. Stonechips on windscreen. Tape holding windscreen trim on RH A pillar. CD player not working. Remote locking not working. Image Image Drives ok. CD (basic test only) Image Image Road Conditions During Test Drive: Dry Central locking Image Engine Timing Mechanism: Cambelt Fewersing camera Image Evidence of Cam Belt Replacement: Yes Kms: 137,512 Sat. Nav. (basic test only) Image							Air Conditioning / Heater			
Seats Poor Head lights ✓	lasta di su C						Operation		~	
Seats Average Indicators V							Electrical / Accessories			
Carpets Average Panels Poor Dashboard Average Carpets Average Carpets Average Carpets Average Carpets Average Carpets V Dashboard Average Carpets V Wipers (front & rear) V Window winder FR V Vindow winder RR V Vindow winder RR V Vindow winder RR V Vindow winder RR V Rear view mirrors V Readio (basic test only) V CD (basic test only) V Vindow ref Ress 1 Road Conditions During Test Drive: Dry Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 137,512	Seats	Poor					Head lights	~		
Panels Poor Dashboard Average Dashboard warning lights ✓ Implicators Implicators ✓ Implicators Implicators ✓ Implicators Implicators Implicators Implicators ✓ Implicators Implicators Implicators Implicators Implicators ✓ Implicators	Carpote	Average					Tail lights	~		
Panels Dashboard Average Wipers (front & rear) ✓ <td>Carpets</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Indicators</td> <td>~</td> <td></td> <td></td>	Carpets						Indicators	~		
Dashboard Average Dashboard Window winder FL ✓ I General Comments ✓ I Vindow winder FR ✓ I LR seatbelt not retracting. Both rear door cards have damage. Tailgate rubber damaged. Rust in tailgate. Stonechips on windscreen. Tape holding windscreen trim on RH A pillar. CD player not working. Remote locking not working. ✓ I ✓ I Drives ok. Rear view mirrors ✓ I I I Road Conditions During Test Drive: Dry ✓ I I I Engine Timing Mechanism: Cambelt Kms: 137,512 I I Reversing camera I ✓ I I I	Panels	Poor					Dashboard warning lights	~		
DashboardImage: Construct of the section		Average					Wipers (front & rear)	~		
General Comments Window winder RL V Image: Comments LR seatbelt not retracting. Both rear door cards have damage. Tailgate rubber damaged. Rust in tailgate. Stonechips on windscreen. Tape holding windscreen trim on RH A pillar. CD player not working. Drives ok. Window winder RR V Image: Comments Drives ok. Radio (basic test only) V Image: Comments	Dashboa	ra					Window winder FL	~		
LR seatbelt not retracting. Both rear door cards have damage. Tailgate rubber damaged. Rust in tailgate. Stonechips on windscreen. Tape holding windscreen trim on RH A pillar. CD player not working. Remote locking not working. Window winder RR V I Drives ok. Rear view mirrors V I I Road Conditions During Test Drive: Dry I I Engine Timing Mechanism: Cambelt Yes Kms: 137,512 Sat. Nav. (basic test only) I V I Reversing camera I I I I I							Window winder FR	~		
Stonechips on windscreen. Tape holding windscreen trim on RH A pillar. CD player not working. Remote locking not working. Window Winder KK V I Rear view mirrors V I I Drives ok. CD (basic test only) V I I Road Conditions During Test Drive: Dry I I I Engine Timing Mechanism: Cambelt Kms: 137,512 I I Evidence of Cam Belt Replacement: Yes Kms: 137,512 I I							Window winder RL	~		
locking not working. Rear view mirrors ✓							Window winder RR	~		
Drives ok. Radio (basic test only) ✓				tiini on kri A pilldf.		ining. Nelliole	Rear view mirrors	~		1
CD (basic test only) I Number of keys 1 Road Conditions During Test Drive: Dry Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 137,512	Drives ek						Radio (basic test only)	~		
Road Conditions During Test Drive: Dry Central locking Image: Central locking Engine Timing Mechanism: Cambelt Remote locking Image: Central lo	Drives ok.						CD (basic test only)		~	
Initial Conditions During Test Drive: Dry Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 137,512							Number of keys	1		1
Initial Conditions During Test Drive: Dry Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 137,512	Road Con	ditions During Test	t Drive:	Dry]	,			
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 137,512 Reversing camera ✓							<u>_</u>		~	1
Evidence of Cam Belt Replacement: Yes Kms: 137,512	Engine Ti	ning Mechanism:	Cambelt	t					•	~
	Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 13	7,512		-		
Inspected by: Roger King Date: 10 Jul 2019		•	-							
	Inspecte	d by: Roger King					Date: 10 Jul 201	9		