

Report ID: 19,613,053 Version: 1 22 Jul 2019 Created:

Make:	Volkswagen	Model:	Beetle	Body Style:	Sedan		Pass	Fail	N/A
Year:	2000	<b>Registration:</b>	GMF365	Reg Expiry:	01 Nov 2019	Engine			1
WoF Expiry:	07 Sep 2019	Odometer:	100,946 Kms	Good No:	19613053	Oil level	~		
VIN:	WVWZZZ9CZ1M6014	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		1
						Performance	~		+
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise		~	-
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior t	o purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S	V	S D PT		SDW	Performance	~		
Key:		6	SUPI	-0 <sup>1</sup>	SD W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent R = rust	S PT C SC			715	S PT W	Operation	~		
R = rust PT = paint defe				$\left( \left  \right\rangle \right)$		Noise	~		+
C = crack				$+ \mathbf{\nabla}$	D R PT SC	Clutch	~		+
P = pin dent	HIS				74114	CV joints	~		+
* = decals PT SC 919 S PT						Wheel bearings	~		+
SC = stone chips						Brakes	-		
W = significant scuffs S PT W S D PT W S D						Performance	~		T
Dealerteen		Note: son	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Front grill alignment Fuel cap alignment									 
Left rear license plate light surround paint defect						Right front		, 4	mm
Centre caps missing Chips and small crack windscreen						Left rear		5	mm
						Right rear			
Conditions During Body Inspection: Dry						Right rear 6 mm   Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Check engir	-	•				Suspension performance	~		1
Wing mirror adjustor nob broken						Steering performance	~		
Centre console lid broken Glovebox handle missing						Shock absorbers	~		
Front license plate surround missing and plate inside car						Air Conditioning / Heater	•		
Engine/gea	rbox oil leak					Operation	~		1
Interior Comments						Electrical / Accessories			
Seats marks, front seats worn/rip						Head lights	~		1
Jeans						Tail lights	~		-
Carpets	marks					Indicators	~		+
Panels	loose, ma	arks				Dashboard warning lights	-	~	+
raneis						Wipers (front & rear)	~	•	+
Dashboa	rd vent con	trols broken, loose	e parts			Window winder FL	~		+
						Window winder FR	~		+
<u>Gene</u> ral C	<u>Comments</u>					Window winder RL	-		~
Starter motor noisy at start up						Window winder RR			~
						Rear view mirrors		~	+
						Radio (basic test only)	~	•	+
						CD (basic test only)	~		+
						Number of keys	2		<u> </u>
Road Conditions During Test Driver						Central locking	2 V		T
Road Conditions During Test Drive: Dry						Remote locking	~		+
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	-		<i>v</i> <i>v</i>
	•	•							<b>r</b>
Inspected	d by: John Lindsay					Date: 22 Jul 201	9		

I have read and understood this condition guide.

Name: .....

Signature: .....