

Report ID: 19,820,883 Version: 1 29 Oct 2019 Created:

Make:	Foton	Model:	Tunland	Body Style:	Utility		Pass	Fail	N/A
Year:	2018	Registration:	LCU754	Reg Expiry:	17 Jan 2020	Engine			
WoF Expiry:	18 Jan 2021	Odometer:	43,461 Kms	Good No:	19820883	Oil level	~		
VIN:	LVAV2MBBXHJ030206	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles a		heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	ical inspection prior to	purchase and th	his can be arranged f	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SC SC		S SC	Radiator / Hoses (visual)	~		
S = scratch	STE	A U			Xa.	Transmission	•		
D = dent	sc 6/6					Operation	~		
R = rust PT = paint def					JHIH	Noise	~		
C = crack				+		Clutch	~		
P = pin dent						CV joints	~		
* = decals	sc 916			The	ETP SSC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S SC						Performance	~		
		Note: som	e defects & blemishe	s may not be disn	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftyre))
LR flare is damaged and not fitting correctly. Both rear mudflaps are missing. Tailgate handle is damaged and tailgate not opening. Holes in deck liner. Small dent on RH C pillar. Stonechips on windscreen. Bumper lamps						Tyres (lowest observed tread depth of tyres)Left front9pmm			
not going.						Right front			mm
LR door body rubber is worn. Has jack but no tools.						Left rear		-	
								9 mm	
Conditions During Body Inspection: Wet						Right rear	9 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Front half of front guard liners missing on both sides. Engine splash guard is bent.						Suspension			
	i nont guara inters miss	sing on both side	s. Engine spiasir guar	a is bent.		Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		
	-					Window winder FL	~		
Concrol						Window winder FR	~		
General Comments Remote locking not working.					Window winder RL	~			
					Window winder RR	~			
Drives well.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
Engine T:	ning Machaniana	T:	- hain			Remote locking		~	
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte	d by: Roger King					Date: 29 Oct 20	10		
inspecte	a by. Hoger King						. ,		

I have read and understood this condition guide.

Name:

Signature: