

Basic Vehicle Condition Guide

Report ID: 19,820,952

Pass

Version: 2

Engine

Oil level

Created: 03 Oct 2019


Fail

N/A

Make: Model: Holden Colorado **Body Style:** Utility Year: 2015 Registration: JMG185 Reg Expiry: 23 Nov 2019 **Odometer:** WoF Expiry: 03 Oct 2020 105,175 Kms **Good No:** 19820952 VIN: MMU148MK0GH6194 Next Service: 107000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Water inside Left headlight need attention

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Underbody very muddy need further investigation

Interior Comment	<u>'S</u>
Seats	Good
Carpets	Average
Panels	Good
Dashboard	Good

General Comments

Inspected by:

4wd

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Bobby Zhong

Evidence of Cam Belt Replacement: No Kms:

~		
~		
~		
		•
~		
~		
~		
•	•	•
~		
~		
		~
~		
~		
		•
~		
~		
d deptl	n of tyr	es)
	4	mm
	5	mm
5		mm
5		mm
	Yes	
·		
V		
V V		
\(\times \)		
\(\times \)		
<i>V V V</i>		
\(\times \)		
\(\times \)		
\(\times \)		
\(\times \) \(\t		
~		
~		
V V		
V V		
~		
ン ン ン ン		
V V V V		
\(\times \) \(\t		
\(\times \) \(\t		
\(\times \) \(\t		
\(\times \) \(\t		
	V V V V V ddeptl	5 5 5

I have read and understood this condition guide.

Name			

03 Oct 2019

Reversing camera