

Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| Report ID: | 19,828,084 | | | |
|------------|-------------|--|--|--|
| Version: | 1 | | | |
| Created: | 04 Oct 2019 | | | |

| Make: | Mazda | Body Style: | Wagon |
|------------------------------------|--------|-------------|-------------------|
| Model: | Atenza | VIN: | 7AT0C139X19100099 |
| Year: | 2008 | Odometer: | 47,429 Kms |
| Road Conditions During Test Drive: | Dry | | |

| Ele | ctrical | 30 | Fuel Flap Release | | Coc | ling System | | Ext | erior | |
|-----|---------------------------|-----|--|----------|------|-------------------|----------|--------------|--------------------------------|-----------|
| 1 | Battery | 31 | Reversing Camera | • | 55 | Coolant Conditio | n 🗾 | 78 | Under Carriage | Good |
| 2 | Headlights | 32 | USB Port | • | 56 | Performance | | 79 | Sun Roof Operation | • |
| 3 | Tail Lights | 33 | Window Lock Switch | | 57 | Radiator/Hoses (v | risual) | 80 | Front Windscreen (no chips) | Good |
| 4 | High Stop Light | Tra | nsmission and Drive | | Sus | pension | | 81 | Back Windscreen (no chips) | Good |
| 5 | Front Right Indicators | 34 | Operation | | 58 | Suspension Perfo | ormance | 82 | Side Windows (no chips) | Good |
| 6 | Front Left Indicators | 35 | Noise | | 59 | Steering Perform | ance | 83 | Front Wiper Blades | Good |
| 7 | Rear Right Indicators | 36 | Clutch | • | 60 | Shock Absorbers | | 84 | Rear Wiper Blade | Good |
| 8 | Rear Left Indicators | 37 | CV Joints | | Wh | eels and Tyres | | 85 | R/H Mirror | Good |
| 9 | Reversing Lights | 38 | Wheel Bearing | | 61 | Left Front | 7 mm | 86 | L/H Mirror | Good |
| 10 | Rear Reflectors | 39 | Wheel Balance | | 62 | Right Front | 7 mm | 87 | L/F Guard | Good |
| 11 | Hazard Lights | 40 | Gearbox (Manual) | • | 63 | Left Rear | 7 mm | 88 | R/F Guard | Good |
| 12 | Courtesy Lights | 41 | Engine Timing Timing | Chain | 64 | Right Rear | 7 mm | 89 | L/H Doors | Good |
| 13 | Dashboard Lights | 42 | Evidence of Cam Belt Replacement Not Ap | plicable | 65 | Spare | Yes | 90 | R/H Doors | Good |
| 14 | Dashboard Dimmer Switch • | 43 | Replaced at (odometer reading) | | 66 | Tools | | 91 | L/H Sill | Good |
| 15 | Number Plate Light | Bra | ıkes | | Inte | rior | | 92 | R/H Sill | Good |
| 16 | Dashboard Warning Lights | 44 | Front Brakes | | 67 | AC Operation | | 93 | Boot/Tail Gate | Good |
| 17 | Speedo | 45 | Rear Brakes | | 68 | Heater Fan | | 94 | Front Bumper | Good |
| 18 | Odometer | 46 | Handbrake | | 69 | Seatbelts | | 95 | Rear Bumper | Good |
| 19 | Rev Counter | Key | s and Locking | | 70 | Horn | | 96 | Roof | Good |
| 20 | Fuel Gauge | 47 | Central Locking | | 71 | Seat Heaters | • | 97 | Bonnet | Good |
| 21 | Wipers Front/Rear | 48 | Remote Locking | | 72 | Sun Visors | | 98 | Fuel Cap | |
| 22 | Window Opener FL | 49 | Number of Keys 1 | | 73 | Sun Visors Lights | /Mirrors | 99 | Mud Flaps | |
| 23 | Window Opener FR | Eng | gine | | 74 | Seats | Average | 100 | WOF | X |
| 24 | Window Opener RL | 50 | Oil Level | | 75 | Carpets | Average | | | |
| 25 | Window Opener RR | 51 | Smokes and Fumes | | 76 | Panels | Average | _ | | |
| 26 | Rear View Mirrors | 52 | Performance | | 77 | Dashboard | Average | | | |
| 27 | Radio (Basic Test Only) | 53 | Noise | | | | | Turn | ers Certification K | ey: |
| 28 | CD (Basic Test Only) | 54 | Starter Motor | | | | | √= F ×= F | | |
| 29 | Boot Open Switch | | | | | | | | ·aii Not applicable for thi | s vehicle |

| Inspected by: | John Lindsay | Date: | 04 Oct 2019 | | | | | |
|--|--------------|------------|-------------|--|--|--|--|--|
| I have read and understood this condition guide: | | | | | | | | |
| Name: | | Signature: | | | | | | |