

Basic Condition Guide

•	Report ID:	21,385,348	Version:	2
	Created:	03 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	/		
Smoke & fumes	~		
Engine performance	V		
Noise	1		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	~		
Noise	/		
Clutch	1		
CV joints			V
Wheel bearings	/		
Brakes			
Performance	•		
Hand brake	/		
Tyres (lowest observed tread d	epth of	tyres)	
Left front		10	0.0 mm
Right front		10).5 mm
Left rear		10	0.0 mm
Right rear		10	0.5 mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	•		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	•		
Electrical / Accessories	ı	,	
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights		/	
Wipers (front & rear)	•		
Window winder FL	•	ļ	
Window winder FR	•		
Window winder RL	•		
Window winder RR	•		
Rear view mirrors	•	ļ	
Radio (basic test only)	•		
CD (basic test only)	•		
Number of keys	1	,	
Central locking	•		
Remote locking	•		
Sat. nav. (basic test only)			'
Reversing camera			

		,	
Make:	Ford	Model:	Ranger
Body Style:	Utility	Year:	2014
Rego No.:	HNY935	Rego Expiry:	23 Jan 2026
WoF Expiry:	07 Aug 2026	Odometer:	229,456 Kms
Good No.:	21385348	VIN:	MNAUMFF50EW275267
Next Service:	243,000	Service History:	No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key R = Rust* = DecalsS = ScratchC = CrackW = Significant scuffs D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Large stone chips in windscreen

Antenna mount on roof. Antenna mount on side of cab

Dent in left cab corner. Minor dents in back of cab

Paint worn in drivers door sill

Under Carriage and Under Ronnet Inspection Comment	ς .
Conditions During Body Inspection Dr	У

Interior Comments

Seats:	Drivers seat torn
Carpets:	Average
Panels:	Average
Dashboard:	Average

General Comments

Check engine light - scanned, EGR valve fault

Traction control light

Holes in centre console

Road Conditions During Test Drive		Dry
Engine Timing Mechanism		Timing Chain
Evidence of Cam Belt Replacement		Yes No Kms
Inspected by:	Samuel Weir	
Published by:	Darren Beban	
Inspection Date:	04 Nov 2025	

have read and understood
this condition quide

NAME			

Drv

S	IG	N	Δ	TΙ	П	R	F	