

Basic Condition Guide

•	Report ID:	22,925,390	Version:	2
	Created:	01 Dec 2025		


	ОК	Requires Attention	N/A
Engine			
Oil level	V		
Smoke & fumes	V		
Engine performance	V		
Noise	V		
Coolant condition	1		
Cooling performance	1		
Radiator / Hoses (visual)	1		
Transmission			
Operation	V		
Noise	/		
Clutch			~
CV joints	/		
Wheel bearings	/		
Brakes			
Performance	V		
Hand brake	1		
Tyres (lowest observed tread	depth of	tvres)	
Left front			6.0 m
Right front			6.0 m
Left rear			7.0 m
Right rear			7.0 m
Spare	Yes		
Suspension			
Suspension performance	1		
Steering performance	/		
Shock absorbers	1		
Air Conditioning / Heater			
Operation	V	Ι	
Electrical / Accessories			
Head lights	V		
	1		
Tail lights Indicators	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
	1		
Dashboard warning lights			
Wipers (front & rear)	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder FL	_		
Window winder FR	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder RL			
Window winder RR	<i>V</i>		
Rear view mirrors	<i>V</i>		
Radio (basic test only)			
CD (basic test only)	1		
Number of keys	1	1	
Central locking	-		
Remote locking	/		
Sat nav (basis tost only)		1	l

Make:	Holden	Model:	Equinox
Body Style:	SUV	Year:	2018
Rego No.:	LNW815	Rego Expiry:	12 Dec 2025
WoF Expiry:	27 Nov 2026	Odometer:	121,779 Kms
Good No.:	22925390	VIN:	3G0AX7EX4JS600591
Next Service:	123,000 Kms	Service History:	Yes

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key

S = ScratchR = RustC = Crack* = Decals W = Significant scuf D = DentPT = Paint defect P = Pin dentSC = Stone Chips



Note: some defects and blemishes may not be displayed in the diagram

Body Inspection Comments

Left front door has model badge ripped off from dent impact. Windscreen has stone chip.

Conditions During Body Inspection	Dry		
Under Carriage and Under Ronnet Inspection Comments			

Left front Axle seal leaking.

Interior Comments			
Seats: Average			
Carpets:	drivers foot rest hole in carpet.		
Panels:	Average		
Dashboard:	Average		

General Comments

Air conditioning and heating systems good temperature along with reversing camera and sat nav working at inspection. Headlining has a hole above the driver. Drivers and right passenger doors sound like they have something loose in the door

WITEIT CIO	when closing.				
Road Conditions During Test Drive		Dry			
Engine Timing Mechanism		Timing Chai	in		
Evidenc	Evidence of Cam Belt Replacement		Yes	No	Kms
Inspecto	ed by:	Finlay Lemmens			
Publishe	ed by:	Amanda Loader			
Inspection	on Date:	03 Nov 2025			

П	nave	read	and	unde	rstood
tł	nis co	nditi	on a	uide	

NAME		

GNATURE			

Sat. nav. (basic test only) Reversing camera