

Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| Report ID: | 23,774,827 |
|------------|-------------|
| Version: | 1 |
| Created: | 24 Jul 2023 |

| Make: | Toyota | Body Style: | Hatchback |
|------------------------------------|--------|-------------|-------------------|
| Model: | Passo | VIN: | 7AT0H650X23197386 |
| Year: | 2014 | Odometer: | 49,824 Kms |
| Road Conditions During Test Drive: | Wet | | |

| Ele | Electrical 30 Fuel Flap Release | | Cooling System | | Ext | Exterior | | | | |
|-----|---------------------------------|-----|-------------------------------------|----------------|----------|---------------------------|------|------------|--------------------------------|-----------|
| 1 | Battery | 31 | Reversing Camera • | | 55 | Coolant Condition | | 78 | Under Carriage | Good |
| 2 | Headlights | 32 | USB Port | | 56 | Performance | | 79 | Sun Roof Operation | • |
| 3 | Tail Lights | 33 | Window Lock Swit | tch | 57 | Radiator/Hoses (visual) | | 80 | Front Windscreen (no chips) | Good |
| 4 | High Stop Light | Tra | nsmission and D | Prive | Sus | Suspension | | 81 | Back Windscreen (no chips) | Good |
| 5 | Front Right Indicators | 34 | Operation | | 58 | Suspension Performance | | 82 | Side Windows (no chips) | Good |
| 6 | Front Left Indicators | 35 | Noise | | 59 | Steering Performance | | 83 | Front Wiper Blades | Good |
| 7 | Rear Right Indicators | 36 | Clutch | | 60 | Shock Absorbers | | 84 | Rear Wiper Blade | Good |
| 8 | Rear Left Indicators | 37 | CV Joints | | Wh | eels and Tyres | | 85 | R/H Mirror | Good |
| 9 | Reversing Lights | 38 | Wheel Bearing | | 61 | Left Front | 4 mm | 86 | L/H Mirror | Good |
| 10 | Rear Reflectors | 39 | Wheel Balance | | 62 | Right Front | 4 mm | 87 | L/F Guard | Good |
| 11 | Hazard Lights | 40 | Gearbox (Manual) |) • | 63 | Left Rear | 5 mm | 88 | R/F Guard | Good |
| 12 | Courtesy Lights | 41 | Engine Timing | Timing Chain | 64 | Right Rear | 5 mm | 89 | L/H Doors | Good |
| 13 | Dashboard Lights | 42 | Evidence of Cam Belt Replacement | Not Applicable | 65 | Spare | Yes | 90 | R/H Doors | Good |
| 14 | Dashboard Dimmer Switch | 43 | Replaced at (odometer reading) | | 66 | Tools | | 91 | L/H Sill | Good |
| 15 | Number Plate Light | Bra | akes | | Interior | | 92 | R/H Sill | Good | |
| 16 | Dashboard Warning Lights | 44 | Front Brakes | | 67 | AC Operation | | 93 | Boot/Tail Gate | Good |
| 17 | Speedo | 45 | Rear Brakes | | 68 | Heater Fan | | 94 | Front Bumper | Good |
| 18 | Odometer | 46 | Handbrake | | 69 | Seatbelts | | 95 | Rear Bumper | Good |
| 19 | Rev Counter | Key | ys and Locking | | 70 | Horn | | 96 | Roof | Good |
| 20 | Fuel Gauge | 47 | Central Locking | | 71 | Seat Heaters • | | 97 | Bonnet | Good |
| 21 | Wipers Front/Rear | 48 | Remote Locking | | 72 | Sun Visors | | 98 | Fuel Cap | |
| 22 | Window Opener FL | 49 | Number of Keys 1 | | 73 | Sun Visors Lights/Mirrors | | 99 | Mud Flaps | |
| 23 | Window Opener FR | Eng | gine | | 74 | Seats | Good | 100 | WOF | V |
| 24 | Window Opener RL | 50 | Oil Level | | 75 | Carpets | Good | | | |
| 25 | Window Opener RR | 51 | Smokes and Fume | es 🗹 | 76 | Panels | Good | _ | | |
| 26 | Rear View Mirrors | 52 | Performance | | 77 | Dashboard | Good | | | |
| 27 | Radio (Basic Test Only) | 53 | Noise | | | | | Turn | ers Certification K | ey: |
| 28 | CD (Basic Test Only) | 54 | Starter Motor | | | | | ✓=F ×=F | | |
| 29 | Boot Open Switch | | | | | | | | Not applicable for thi | s vehicle |

| Inspected by: | Dale Dryden | Date: | 24 Jul 2023 | | | | |
|--|-------------|------------|-------------|--|--|--|--|
| I have read and understood this condition guide: | | | | | | | |
| Name: | | Signature: | | | | | |