

I have read and understood this condition guide.

Report ID: 24,981,220 6 Version: 07 May 2025 Created:

Signature:

| Make: | Mazda | Model: | Mazda6 | Body Style: | Wagon | | Pass | Fail | N/A | |
|--|---|----------------------|------------------------|---------------------|-----------------------|--|--------------|------|--------------------|--|
| Year: | 2009 | Registration: | FDB53 | Reg Expiry: | 15 Aug 2025 | Engine | | 1 | | |
| WoF Expiry: | 30 Dec 2025 | Odometer: | 224,253 Kms | Good No: | 24981220 | Oil level | ~ | | | |
| VIN: | JM0GH10F100127956 | Next Service: | 234000kms | Service Histor | y: Yes | Smoke & fumes | ~ | | | |
| | | | | | | Performance | ~ | | | |
| | port is not a warranty a quide only. Conside | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechan | lical inspection prior to | purchase and th | his can be arranged fo | or an additional of | charge. | Coolant condition | ~ | | | |
| | S S | | S SP | | S | Performance | ~ | | | |
| Key: | | -0 | | -(0)- | | Radiator / Hoses (visual) | ~ | | | |
| S = scratch D = dent | | | | | | Transmission | Transmission | | | |
| D = dent R = rust S SC D S | | | | | | Operation | ~ | | | |
| PT = paint defect | | | | | | Noise | ~ | | | |
| C = crack | | | | | PT | Clutch | | | ~ | |
| P = pin dent | CREE HIS | | | | 7414 | CV joints | ~ | | | |
| * = decals SPT SC 9 9 SPT | | | | | | Wheel bearings | ~ | | | |
| SC = stone chips | | | | | | Brakes | | | | |
| W = significant scuffs S SC S S P SC S P SC S W | | | | | | Performance | ~ | | | |
| Podulac | | Note: som | ne defects & blemishe | s may not be disp | blayed in the diagram | Hand Brake | ~ | | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | | |
| Stone chips in windscreen. | | | | | | Left front 6 mm | | | | |
| | | | | | | Right front | | 5 | mm | |
| | | | | | | Left rear | | 8 | mm | |
| Conditions During Body Inspection: | | | | | | Right rear | | 8 | mm | |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| | - | | | | | Suspension performance | ~ | | | |
| | | | | | | Steering performance | ~ | | | |
| | | | | | | Shock absorbers | ~ | | | |
| | | | | | | Air Conditioning / Heater | • | | | |
| | | | | | | Operation | | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | | |
| Seats Good | | | | | | Head lights | ~ | | | |
| | 0000 | | | | | Tail lights | ~ | | | |
| Carpets | Average | | | | | Indicators | ~ | | | |
| Panels | Card | | | | | Dashboard warning lights | ~ | | | |
| | Good | | | | | Wipers (front & rear) | ~ | | | |
| Dashboa | rd Average | | | | | Window winder FL | ~ | | | |
| | I | | | | | Window winder FR | ~ | | | |
| General Comments | | | | | | Window winder RL | ~ | | | |
| Vehicle drove well. | | | | | | Window winder RE | ~ | | | |
| Paint fade/Clear coat lifting on bonnet | | | | | | Rear view mirrors | ~ | | | |
| | - | | | | | Radio (basic test only) | ~ | | | |
| | | | | | | CD (basic test only) | ~ | | $\left - \right $ | |
| | | | | | | Number of keys | 2 | | L | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | 2 | | | |
| Koad Con | ations During Test | Drive: | Dry | | | Remote locking | ~ | | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ | |
| | | | | | | | | | | |
| Inspected by: Rea Symons Date: 07 May 2025 | | | | | | | | | | |
| | | | | | | | | | | |

Name: